



SUPPORTO PER SENSORI LIVELLO

Level sensor support


art. AP9010.00.03

Caratteristiche:

- 1 - per sensori di livello Ø 30 mm
- 2 - specifico per magazzini in tela linea Teksilo
- 3 - installazione semplice

Features:

- 1 - for Ø 30 mm level sensors
- 2 - specific for fabric storage units of the Teksilo line
- 3 - easy to install



Posizione di montaggio
Mounting position

Descrizione e misure supporto per sensori di livello/Level sensors support description and sizes

Il supporto per sensori di livello è specifico per i magazzini della linea Teksilo in tessuto.
Evita il danneggiamento della tela supportando il sensore di livello senza lacerazioni.
Accoglie tutti i sensori capacitivi con Ø 30 mm, come l'art. AP4210.00.01, l'art. AP4210.00.03 o l'art. AP4210.00.04

Semplice da montare, è completo di accessori per l'installazione sul magazzino.

The level sensor support is specific for the fabric storage silos of the Teksilo line.
Protects the cover for being damaged by supporting the level sensor without tears.

Accommodates all capacitive sensors with Ø 30 mm, such as art. AP4210.00.01 or art. AP4210.00.03 or art. AP4210.00.04

Easy to assemble, it includes accessories for installation on the storage silo.

Modello supporto per sensori di livello Level sensor support model	Unità Unit	Art. AP9010.00.03
Peso/Weight	Kg	1,1
Misura/Size A	mm	150
Misura/Size B	mm	150
Diametro interno/inner diameter C	Ø mm	32

